


# SAFETY PROCEDURE

N °

021

LT ADAM DE  
CRAPONNE

RAMO A30 X5P LATHE



Personal protective equipment	<ul style="list-style-type: none"><li>• Overall</li><li>• Safety shoes</li></ul>
	
Machines	<ul style="list-style-type: none"><li>• Mind your hands</li><li>• Put the protective chuck</li></ul>
	
Tools	<ul style="list-style-type: none"><li>• Use an appropriate tool to remove chips (hook or brush)</li></ul>
	
Environment	<ul style="list-style-type: none"><li>• Don't leave anything lying on the floor</li><li>• Keep your work station clean and tidy</li></ul>
	