





**ALCERA GAMBIN 60C  
NC MILLING MACHINE**



<p>Personal protective equipment</p>	<ul style="list-style-type: none"> <li>• Overall</li> <li>• Safety shoes</li> </ul>
	<p><b>Machines</b></p> <ul style="list-style-type: none"> <li>• Follow the procedure before you start any machining work</li> <li>• Close the door of the machine</li> </ul>
	<p><b>Tools</b></p> <ul style="list-style-type: none"> <li>• Use an appropriate tool to remove chips (hook or brush)</li> </ul>
	<p><b>Environment</b></p> <ul style="list-style-type: none"> <li>• Don't leave anything lying on the floor</li> <li>• Keep your work station clean and tidy</li> </ul>
