





ARO SPOT-WELDING MACHINE



<p>Personal protective equipment</p>	<ul style="list-style-type: none"> • Overall • Safety shoes • Safety glasses • Gloves
	
<p>Machines</p>	<ul style="list-style-type: none"> • Mind your hands • Contact lenses are prohibited
	
<p>Tools</p>	<ul style="list-style-type: none"> • Hold the piece properly
	
<p>Environment</p>	<ul style="list-style-type: none"> • Don't leave anything lying on the floor • Keep your work station clean and tidy
